



## Bid Notice Abstract

### Request for Quotation (RFQ)

**Reference Number** 11192514  
**Procuring Entity** BUREAU OF FISHERIES AND AQUATIC RESOURCES CARAGA  
**Title** RFQ-Replace of spareparts ,wheel alignment ,body alignment ,body painting and change oil for Vehicle Toyota Hilux w/ plate no. P4 -1713  
**Area of Delivery** Agusan Del Norte

<b>Solicitation Number:</b>	RFQ-125-2024	<b>Status</b>	<b>Pending</b>
<b>Trade Agreement:</b>	Implementing Rules and Regulations	<b>Associated Components</b>	1
<b>Procurement Mode:</b>	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	<b>Bid Supplements</b>	0
<b>Classification:</b>	Goods	<b>Document Request List</b>	0
<b>Category:</b>	Vehicle Repair and Maintenance	<b>Date Published</b>	29/08/2024
<b>Approved Budget for the Contract:</b>	PHP 174,825.00	<b>Last Updated / Time</b>	28/08/2024 16:28 PM
<b>Delivery Period:</b>	30 Day/s	<b>Closing Date / Time</b>	04/09/2024 17:00 PM
<b>Client Agency:</b>			
<b>Contact Person:</b>	Elvera Base Sayas BAC Secretariat Peñaranda Street, Barangay Taft Surigao City Surigao Del Norte Philippines 8400 63-909-4817511  bac.caraga@bfar.da.gov.ph		

#### Description

Note:

- For queries and requesting (RFQ) form
- visit our website (Caraga.bfar.da.gov.ph)
- Standard form of our RFQ form shall be accepted, herewith attached in post to the PHILGEPS.
- Submit your quotation seal and label with reference number/project title, at BFAR 13 SURIGAO CITY, SURIGAO DEL NORTE
- Attach for the following requirements:
  1. PHILGEPS REGISTRATION
  2. BUSINESS PERMIT
  3. Certificate of Registration (BIR)
  4. Omnibus Sworn Statement

Unit Description Quantity

Replace of spareparts ,wheel alignment ,body alignment ,body painting and change oil for Vehicle Toyota Hilux w/ plate no. P4 -1713

- set Replace Brake shoe 1
- set Wheel Alignment 1
- side Overhaul Brake (Front) 2
- set Replace Wiper Blade 1
- set Replace rain visor 1
- side Replace Rotor Disc (front) 2
- set Replace Brake Pads 1
- set Replace Fog Light Assy 1
- side Replace lower Ball Joint 2
- side Replace Upper Ball Joint 2
- side Replace Lower Bushing 2
- side Replace Upper Bushing 2
- side Replace Rack end 2
- side Replace tie rod end 2
- side Replace Stabilizer Link 2
- side Replace Shock absorber (Front) 2
- side Replace Shock absorber (rear) 2

set change Transmission Oil 1  
set Change Engine Oil 1  
set Replace Fuel filter 1  
set Change Differential Oil 1  
set Repack Clutch Pan 1  
pcs Machine Shop (Press Bushing and Ball joint 12  
set BODY ALIGNMENT: 1  
Front Hood Panel  
Door Panel (Driver side)  
Rear Bumper Panel  
set BODY PAINTING 1  
Door Panel (Driver Side)  
Front Hood Panel  
PARTS  
set Brake Shoe 1  
pcs Brake Fluid 2  
set Caliper Repair Kit 1  
set Wiper Blade (Banana type) 1  
set Rain Visor 1  
pcs Rotor Disc 2  
set Brake Pads 1  
set Fog Light Assy. 1  
pcs Lower Ball Joint 2  
pcs Upper Ball Joint 2  
pcs Lower Bushing 2  
pcs Upper Bushing 2  
pcs Rack End 2  
pcs Tie Rod End 2  
pcs Stabilizer Link 2  
pcs Shock Absorber (Front) 2  
pcs Shock Absorber (rear) 2  
ltr Transmission Oil 6  
ltr Engine Oil (Semi Synthetic) 8  
pc Oil Filter 1  
pc Fuel Filter 1  
ltr Gear Oil 90 5  
pcs Silicon Oil 9  
Assy Rear Bumper Assy 1  
pcs Parts Cleaner 2  
pcs Penetrating Oil 2

**Created by** Elvera Base Sayas

**Date Created** 28/08/2024

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.